T: 0800 8620066 E: support@bisonassist.co.uk



Disability Access Risk Assessment

Conducted at

Wilton Cemetery



Suggested date for review:

November 2025 - or if there are any significant changes, whichever is soonest.

E: support@bisonassist.co.uk



Address of premises: 87 Shaftesbury Road, Wilton SP2

0DU

Responsible person (e.g. employer) or person having control of the premises:

Clare Churchill

Assessor: Billy Fee

Reviewed by: Yan Spink-Herman

Date of disability access risk assessment: 27/11/2024

Site Representative (*):	Date & Time:	Signature:

(*) For responsible person to sign upon receipt of this risk assessment to validate it.

The purpose of this report is to provide a disability access risk assessment for these premises, and, where appropriate, to make recommendations to ensure compliance with the Equality Act 2010. The report does not address the risk to property or business continuity.

This disability access risk assessment should be reviewed by a competent person by the date indicated above or at such earlier time as there is reason to suspect that it is no longer valid, or if there has been a significant change in the matters to which it relates.

T: 0800 8620066 E: support@bisonassist.co.uk



Contents:

Introduction

Risk Assessment Goals

Legislation

Risk Assessment Report

1.0 General Information

2.0 Disability Access Management & Controls

3.0 Visual Inspection & Assessment of Risk

- 3.1 Access & Car Park
- 3.2 Horizontal Circulation
- 3.3 Vertical Circulation
- 3.4 Public Circulation
- 3.5 Signage
- 3.6 Alarms
- 3.7 Toilets
- 4.0 Records
- 5.0 Risk Rating
- 6.0 Action Plan

E: support@bisonassist.co.uk



Introduction

We recently visited your premises at 87 Shaftesbury Road, Wilton SP2 0DU, to carry out a Disability Access Risk Assessment in line with The Equality Act 2010.

The aim of this survey is to assess the risk to life or injury, of those who are disabled, while accessing these premises, and, where appropriate, to make recommendations to ensure compliance with the relevant legislation.

All the recommendations that are made in your report are aiming to account the specific requirements of the site, what is reasonably and practicable with consideration of manpower and budgeting. This risk assessment is only effective if you and your staff act on it. Therefore, in order to achieve compliance, the action recommended in this assessment must be undertaken.

As a result of the disability access risk assessment carried out at Wilton Cemetery, Bison Assist recommends a review to be carried out on November 2025 - or if there are any significant changes, whichever is soonest..

Limitation

The disability access risk assessment was carried out only on parts of the building which were made available on the day.

We will not include in our report any parts of the building which were not made available to our team. Please note that exclusion of such parts does not indicate their absence. While we make every endeavour to ascertain the correct information regarding the site layout and systems, our consultant must rely on staff knowledge and any available relevant documentation. Lack of such knowledge or information may lead to assumptions on the part of the consultant.

Whilst every effort has been made to ensure the accuracy of the content of this document, Bison Assist Ltd will accept no responsibility for any omissions.

E: support@bisonassist.co.uk



About Your Risk Assessor

Your risk assessor was Billy Fee. He holds all the appropriate competencies and experience to undertake this assessment of risk on behalf of Clare Churchill, who is the appointed responsible person in your organisation.

Bison Assist's risk assessors are regularly shadowed on the job. Their work will also be monitored, and their competencies regularly assessed. Find out more about your risk assessor's competencies and experience by emailing support@bisonassist.co.uk.

As your trusted partner in safety, here are some of the accreditations held by Bison Assist:











© Copyright Bison Assist Ltd

All rights reserved. No part of this publication, neither the printed copy or the electronic file, in whole or in part, may be reproduced or transmitted in any form or by any means, electronic or mechanical, including transmittal by email, by the file transfer protocol (FTP), through access by network, by photocopying, by recording, or by any information storage and retrieval system, without written permission from Bison Assist Ltd. The parties stated in this document at the location herein may only use this publication and copies there internally.



Risk Assessment Goals

Goal 1 - Risk Assessment: About Your Report

A risk assessment is typically the starting point on your journey to making your building inclusive for all users, this should contribute to a more comprehensive plan for the effective management and control of safe access, egress and experience for all who work within or visit your building, including those who have disabilities and require additional support.

Here is how we completed your risk assessment:

- Through visual inspection
- Observation of existing policies, procedures, records and other relevant documentation
- By gathering knowledge from members of your team, whilst we were on site.

Goal 2 - Action Plan: Next Steps

Within the report, you will find an Action Plan section. It is vital that this is understood and implemented. Some of these actions may be achieved in house, by your responsible person or a member of your team, others will need to be carried out by specialists with the relevant qualifications, skills and competence. On receipt of this document, should you have any queries or would like any further assistance or advice, please do not hesitate to contact our Support team at support@bisonassist.co.uk.

Please remember, the risk assessment is the beginning of the journey, not the end.

The Health and Safety Executive warns: "A risk assessment is only effective if you and your staff act on it. You must follow through with any actions required and review it on a regular basis".

Goal 3 - Review: Legal Requirements

Risk management should always remain effective. Some risks that are "very low" today, may increase over time, therefore it is important that reviews are carried our annually.

The assessment should be reviewed regularly and, specifically when there is a reason to suspect that it is no longer valid. An indication of when to review the assessment and what needs to be reviewed should be recorded. This may result from, for example:



- A change in legislation.
- Alterations to the building, including internal layout.
- A change of use of premises.
- A significant increase in the number of personnel or the introduction of people with disabilities.
- A significant change to furniture and fittings.
- Receipt of an enforcement or prohibition notice or prosecution for a disability discrimination issue.
- Any situation that may jeopardise the safety of those within the building.

E: support@bisonassist.co.uk



Legislation

It is a legal requirement for every employer to conduct an assessment of the health and safety risks, arising out of their work activity. Under Regulation 3 of the Management of Health and Safety at Work Regulations 1999, the purpose of such assessment is to identify what needs to be done in order to control health and safety risks. Further applicable legislation to Safe Disability Access has been listed in table 1.0 – Applicable Legislation, below:

Legislation applicable to Premises:	Duties Imposed by the Legislation:
Equality Act 2010	Appoint one responsible person to undertake any required preventative and protective control measures
The Management of Health and Safety Regulations 1999	Provide all staff with clear and relevant information on the identified accessibility risks for disabled users and measures taken in order to accommodate them
The Health & Safety at Work Act 1974	Conduct a disability risk assessment of the premises
Lifting Operations and Lifting Equipment Regulations 1998	Identify the safety measures necessary as a result of the disability access risk assessment
The Building Regulations 2010	Implement the safety measures contained within the assessment using risk reduction principles
EN 16005: 2012 Power operated pedestrian door sets. Safety in use. Requirements and test methods	Implement safety arrangements for the continuing control and review of the measures
BS 5839 – Fire detection and alarm systems for buildings.	Comply with the specific requirements of the current regulations
Code of Practice for Thermostatic Mixing Valves	Keep the assessment current through regular review
BS 5499 – Safety signs and symbols	Keep written records of the findings and actions taken
HM Government guidance on Disability Access Risk Assessment	Inform non-employees, such as temporary staff or contractors of the relevant risks to them and relevant safety procedures

T: 0800 8620066 E: support@bisonassist.co.uk



1.0 General Information

1.1 Premises overview	
Description of Building:	Gated building leading to the local burial grounds. Constructed of brick and mortar, this gate house has 4 rooms.
Number of Floors:	2
Main use of premises:	Burial Grounds
Name of Responsible Person:	Clare Churchill
Approximate number of employees at any one time:	1-5
Approximate maximum number of visitors/ occupants/ others:	50+
Persons involved or affected:	Employees, Visitors, Contractors, Members of the public, Others
Are there any vulnerable groups which use the premises?	Yes
Are disabled persons at any risk while accessing the premises?	No

E: support@bisonassist.co.uk



2.0 Disability Access Management & Controls

2.0 Disability Access Management & Controls Has a responsible person been appointed to deal with disability access protocols? Yes

Risk:	Very Low
Do records demonstrate that disability	No
procedures have been defined and	
communicated to relevant staff? (incl. evacuation	
of disabled people in the event of an emergency)	

As an employer it is illegal to discriminate against an existing or potential disabled employee or visitor without justification. To prevent discrimination, the responsible person has the duty to make reasonable adjustments to policies, practices, procedures and/ or premises.

Specific details:	Employees are not commonly on site
Risk:	Low

3.0 Visual Inspection & Assessment of Risk

3.1 Access & Car Parking	
Does the site have any dedicated disabled parking for their premises?	No due to restrictions imposed by the location of the premises
Specific details:	No site specific parking
Do designated external routes appear to be safe to use by pedestrians, including wheelchair users?	No

The duty to make reasonable adjustments is a cornerstone of the Equality Act and requires service providers to take positive steps to ensure that disabled people can access facilities and services. The duty is to make reasonable adjustments to avoid disabled people being placed at a "substantial disadvantage", compared to non-disabled people, when accessing the facilities or services.

E: support@bisonassist.co.uk



Specific detail(s):	No drop kerb leading to gates and the floor was uneven beyond the gate.
Risk:	Medium
Has an adequate level of external emergency lighting been provided?	Not needed/High Street

Risk:	Very Low
Can external directional signage be deemed as	No external directional signage required due to the
adequate?	location of the premises

Risk:	Very Low
Can designated routes to evacuation points be No reached safely by disabled people?	

Evacuation routes should be regularly checked for obstructions and appropriately sign-posted so they can be safely accessed and used by those with disabilities. All the designated evacuation routes should be incorporated in the evacuation plan for the site. Assisted evacuation plans should be separately designed for those with disabilities.

Specific details:	No ramps provided to and from rooms
Risk:	High
Has a drop kerb been provided, external to the	No
building, in order to ease wheelchair accessibility?	

Dropped kerbs allow level access for wheelchair or electric scooter users. These should be provided for areas where people who are having access difficulty because of the height of kerbs are expected to access. Local councils are able to support where necessary upon contact. Consideration should be given to measures to prevent the obstruction of dropped kerbs on uncontrolled crossings by parked vehicles.

Specific details:	No drop kerb.
Risk:	Low

E: support@bisonassist.co.uk



Can the maximum width of pathways be deemed as adequate in order to facilitate safe travel? (if <1.2m should not exceed 6m travel)

Yes

Risk:	Very Low
Where thresholds are greater than 0.2m have	No
ramps (including mobile ramps) been provided?	

E: support@bisonassist.co.uk



3.2 Horizontal Circulation (hallways, entries, exists and landings) & Doors

Can the entrance be deemed prominent against surroundings?

Can the width of the main entrance door be

deemed suitable for all service users?

Yes

Risk:	Very Low
At the time of the inspection, has the entrance been obstructed?	No
Risk:	Very Low
Does the threshold have weather protection available?	Yes
Risk:	Very Low

Risk:	Very Low
Does the site operate mechanically assisted	No
doors?	

Yes

Automatic or powered doors are the preferred option. It can be deemed as best practice that all main entrance doors and doors on circulation routes to be automatically activated with sensors in order to provide an easy way in and out for disabled users.

Low
Yes

Risk:	Very Low
Are internal emergency exit routes adequately lit?	No

E: support@bisonassist.co.uk



All internal emergency exit routes must be adequately lit, so that all users (staff, visitors, contractors) can see along the exit route and evacuate the premises safely. The lighting should have adequate intensity and must be provided in case the normal lighting fails.

Risk:	Low
At the time of inspection, were the hallways and landings free from slip or trip hazards?	Yes
Risk:	Very Low
Is adequate colour contrast provided between floors, walls and doors?	Yes
Risk:	Very Low
Can door handle designs be deemed appropriate for use by those with dexterity problems?	Yes
Risk:	Very Low
Risk: Does the site have an adequate door entry system installed? (900mm above floor level)	Very Low None required
Does the site have an adequate door entry	
Does the site have an adequate door entry	
Does the site have an adequate door entry system installed? (900mm above floor level)	None required
Does the site have an adequate door entry system installed? (900mm above floor level) Risk: Can the width between door frames be deemed	None required Very Low
Does the site have an adequate door entry system installed? (900mm above floor level) Risk: Can the width between door frames be deemed	None required Very Low

3.3 Vertical Circulation (stairs & lifts)

Are internal stairs in good condition and fit for purpose?

No internal stairs



Risk:	Very Low
Does the site have an adequate platform lift installed?	One level (none needed)

Risk:	Very Low
Is there a sufficient number of evacuation chairs provided for the site?	None required

Risk:	Very Low
Does the site have a passenger lift?	One level (none needed)

E: support@bisonassist.co.uk



3.4 Public Circulation (reception, waiting area, lobbies, other rooms)

Have any unshielded obstructions greater than 1m been observed between the entrance route and reception? No reception

Risk:	Very Low
Do floor surfaces appear to be firm and without slips and/or trip hazards?	Yes
Risk:	Very Low
Has the reception area been provided with adequate signage?	No reception
Risk:	Very Low
Have appropriate meet and greet systems been provided?	Not required/ Satisfactory controls in place
Risk:	Very Low
Does the site have an adequate public address system installed?	Not required
Risk:	Very Low
Has the site provided suitable hearing induction loop systems for users?	Not required
Specific details:	None.
Risk:	Very Low

E: support@bisonassist.co.uk



Do wheelchairs have sufficient space for standing and manoeuvring without obstructing door swings?

Yes

Risk:	Very Low
Would it appear that a wheelchair may restrict	No waiting area
other users within the waiting area, taking into	
consideration the furniture position?	

Risk: Very Low

Does it appear that the sitting area in the waiting area is fit for purpose?

No waiting area

Risk: Very Low

3.5 Signage (consider hearing impaired, vision impaired, non-English speaking etc.)

As far as it can be ascertained is signage appropriately located? (Location, Accessibility, Layout, Height etc.)

New Site/ Signage to be added

It is important that signage is located in a suitable position to allow service users can take note of them.

Risk:

Can the font, size of lettering and use of symbols be deemed as appropriate, so that vulnerable groups can easily read them?

Low

New site/ Signage to be added

In order to be deemed as appropriate, text on signs should be clear and simple using sans-serif fonts. Words should not be made up of capital letters only. Consideration should be given to usage of shorter columns that are easier to read and remember. It is recommended to avoid use of long lists of items on signs.

Risk:	Low
Can it be deemed that all the relevant	Yes
signage are visible and well lit?	

E: support@bisonassist.co.uk



Risk:	Very Low
Is sufficient tactile signage provided throughout the site?	Not required/ Staff assist
Risk:	Very Low
Is additional signage that can ease disabled users access required?	No
Risk:	Very Low

3.	.6 Alarms
Are audible alarm systems installed (including	No
smoke detectors)?	

The noise ensures that visually impaired people and those with limited hearing can still detect the need to evacuate. The sound of the alarm must be easy to distinguish from the prevailing noise in the room to prevent misinterpreting the alarm. Alarm noise levels can't exceed 120 A-weighted decibels (dbA).

Risk:	High
Are visible alarm systems installed?	Not required (small site/extra control measures in place)
Risk:	Very Low

E: support@bisonassist.co.uk



3.7 Toilets Are toilets designated for disabled users available on site? No

Equality Act 2010 – Part 3 Service Provision: The responsible person is obliged under the Act to make reasonable adjustments to make their service accessible for all service users. These may include physical adjustments to overcome barriers of access.

Specific details:	A single stall toilet was available on site and was not accessible for those with mobility impairments or wheelchairs due to the step at the door.
Risk:	Medium
Is there good contrast provision between the toilet door, walls and floors?	Yes

Risk:	Very Low
Are facilities, such as washrooms, fitted with TMVs in order to avoid the risk of scalding?	No

Thermostatic mixing valves are recommended to be installed to outlets of which the hot water pose a high scalding risk. One thermostatic mixing valve should be installed per tap and the pipework from the valve to the tap shouldn't be longer than 2m.

Risk:	Low
Can the surface area of the disabled toilet be	Space restricted due to building limitations
deemed adequate for wheelchair access? (clear	
floor area of 2000mm x 2000mm)	

Risk:	Very Low
Have appropriate handrails/ grab rails been	No
installed?	

A counterbalanced single bar hinged support rail with an integral toilet roll holder should be provided. All support fittings should be designed to withstand an ultimate of 15kN (kiloNewtons).

Specific details:	No grab rails were installed.
Risk:	Medium

E: support@bisonassist.co.uk



Is the	toilet	located	at a	suitable	height	to	allow	
easy 1	transfe	er?						

Risk:	Very Low
Are hand basins installed at an adequate height to facilitate users with disabilities?	Not applicable due to space restrictions
Risk:	Very Low
Does the toilet have an emergency assistance system installed?	Not applicable due to the nature of the building

Yes

Risk: Very Low

Has a mirror been installed at a suitable height? No mirror

A full-length safety mirror should be fitted, set at maximum 300mm above floor level.

Risk:	Low
Can the level of the lighting be considered adequate?	No

Lightings operated by sensors are preferred, but not mandatory. Light levels should be maintained to an adequate level and monitored to avoid flicker.

Specific details:	No light fittings in this side of the building.
Risk:	Medium
Is the light switch situated at a suitable height?	No

Light switches should be installed no higher than 900mm above floor level. Where the light is operated by a pull cord it should be white coloured, and its end should be 450mm above the floor. Pull rings should be installed at the end and at 900mm above floor level.

Specific details:	Light switch illuminated the groundsman's store and not the toilet area. The switch is installed at approximately 1700mm.
Risk:	Low

E: support@bisonassist.co.uk



4.0 Records

4.0 Records		
Has an equality policy been observed for the site?	Yes	
Risk:	Very Low	
Do records show that staff receive adequate periodic training in order to deal with people with disabilities?	No	

Disability awareness training should be provided periodically to all staff members who work alongside or/ and expected to offer support to disabled users.

Risk:	Low
Do records show that the site is gathering	No
additional information for visitors and	
contractors in order to ensure that any potential	
additional support required for site attendance is	
met?	

The site should not discriminate when gathering visitors and contractor's information, therefore it is recommended that general "site attendance" forms are used. It is important to gather relevant information from anyone attending site in order to analyse how well commitments to different groups of people are met. Gathering relevant information supports in making important decisions when it comes to physically adapting the site for accommodating users with special requirements. Such information should also be used in referring any potential disabled users somewhere else in case there are building restrictions that can limit special user requirements.

Risk:	Low
Does the site have adequate service provision for	No
accommodating disabled users? (e.g. closer to	
exists or escape routes)	

Equality Act 2010 – Part 3 Service Provision: The responsible person is obliged under the Act to make reasonable adjustments to make their service accessible to members of the public. These may include physical adjustments or adjustments to policies, practices or procedures to overcome barriers of access.

E: support@bisonassist.co.uk



Observations: No signage was installed for service users as there was no requirement. There was no light fixture in the toilet area and the switch installed in this area illuminated the groundsman's store room. The groundsman's store room has been discounted from this assessment as the room is padlocked with access restricted to relevant persons only.



5.0 Risk Rating

Risk Level Please follow target dates if not advised otherwise

Very Low Risk

No remedial action required at the time of the Risk Assessment.

Very low likelihood for somebody with disabilities to get injured while on site. There are no actions required, however processes and protocols should be monitored in other to ensure no increase in the risk level.

Low Risk

Recommended actions to be completed within **6 to 12 MONTHS.**

Usually low likelihood for somebody with disabilities to get injured while on site. Recommended actions are completed within 6 to 12 months. These are usually actions which represent or suggest minor improvements to existing procedures or conditions in line with best practice guidance.

Medium Risk

Recommended actions to be completed within **3 MONTHS.**

Normal disability access hazards for this type of premises, generally subject to appropriate controls (other than mirror shortcomings). Recommended actions are completed within 3 months. These are usually actions that represent a medium level of risk to existing procedures or conditions which if ignored could escalate to high risk, therefore should be targeted.

High Risk

Recommended actions to be completed **IMMEDIATELY.**

Lack of adequate controls applied to one or more significant disability access hazards, such as to result in significant increase in likelihood of somebody with disability to get injured while on the premises. Recommended actions are completed as soon as reasonably practicable. These actions are classed as URGENT and IMPORTANT actions and directly relate to loss of control and exposure to unacceptable levels of risk

E: support@bisonassist.co.uk



6.0 Action Plan

The remedial actions table highlights the issues identified during the assessment of Disability Access risk. It is highly recommended the actions priority is followed.

Once the actions have been completed, these are required to be confirmed through signature by the designated responsible person. Completion of actions will lower the Disability Access risk.

Action:	Priority:	Completion date:	Completed by:
Reasonable adjustments to external routes are advised to be made in order to avoid disabled people being placed at a "substantial disadvantage", compared to non-disabled people, when accessing the facilities or services.	Medium		
Regularly check evacuation routes for obstructions and appropriately sign- posted. Designated evacuation routes should be incorporated in the evacuation plan.	High		
Consideration should be given for drop kerbs in areas where people who are having access difficulty. Measures should be in place to prevent obstruction of dropped kerbs.	Low		



Consideration should be given to installing automatic or powered doors.	Low	
It is recommended that internal emergency exit routes adequately lit.	Low	
Text on signs should be clear and simple using sans-serif fonts. Words should not be made up of capital letters only.	Low	
or capital feecers only.		
It is recommended that audible alarm systems be installed.	High	
It is advised toilets designated for disabled users to be made available on site.	Medium	
It is advised TMVs to be fitted in washroom of which the hot water pose a high scalding risk.	Low	



It is recommended appropriate handrails/ grab rails to be installed.	Medium	
A full-length safety mirror should be fitted, set at maximum 300mm above floor level.	Low	
Lightings operated by sensors are preferred, but not mandatory. Light levels should be maintained to an adequate level and monitored to avoid flicker.	Medium	
It is recommended that the light switch to be situated at a suitable height.	Low	
Recommend disability procedures to be defined.	Low	
Disability awareness training should be provided periodically to all staff members who work alongside or/ and expected to offer support to disabled users.	Low	



It is recommended that general "site attendance" forms are used, in order not to discriminate when gathering visitors and contractor's information.	Low	
Ensure reasonable adjustments are made to service accessible to members of the public.	Low	

E: support@bisonassist.co.uk



Appendix - Photos

Please find below pictures taken on the day of the assessment:

