

## Wilton Town Council

## Wilton Flood Group

## **Meeting Notes and Actions**

The Council Offices
Kingsbury Square
Wilton SP2 0BA

Meeting held in the COUNCIL CHAMBER, COUNCIL OFFICES, KINGSBURY SQUARE, WILTON on FRIDAY 21 FEBRUARY, 2020 at 10.30am

01722 742093

**Present:** 

Email the clerk

Cllr Ivan Seviour (Mayor)
Cllr Andy Kinsey (Deputy Mayor)
Cllr Pauline Church (Chair)
Cllr Peter Edge (Flood Warden)

Cllr Lee Glyde Anthony Brown-Hovelt (Flood Warden) Rachel Ashton-Brown (Flood Warden) Steve Milton (Town Clerk)

Wilton TC Website

WTC = Wilton Town Council EA = Environment Agency WC = Wiltshire Council HE = Highways England WE = Wilton Estate GRS = Grovely Riding Centre

Issue Action Who **Progress** 1. Flood Barrier: Crow Lane SM reported that the EA team had been on site on 20/2 to review the installation of the flood barrier. The barrier was reconfigured and will remain in place until flood risks recede. Water level had reached above 7' on the depth gauge at Naish Felts Bridge on 21/2 and was lapping over That the EA be requested to the bank. The Group considered that the best long-term release funding for the wall solution would be to build a 75cm wall along the river bank at Crow Lane. This has long in this location. Plans had been produced by the EA as part EΑ been identified as a high risk of the Wilton funding package that had included the Castle area and work is now Meadow bund. The Group considered that these issues urgently required. should be de-coupled, given that there had been no flooding in Castle Meadow. The Group noted that funding for the wall may be possible through the development at Naish Felts with possible conditions imposed on development. 2. **Vulnerable Residents - North Street** A B-H reported that he had issued Floodsax™ to two No further action required WTC residents in the North Street area.

## 3. Willow Trees in Wylye River Channel

A B-H reported that a number of willow trees had established in the Wylye River channel at Riverside, these could obstruct flow and add to current flood risks. Land owned by WC.

WC be asked to remove the trees and tree stumps from the River channel.

WC

4.	Obstruction at Wylye Bridge, North Street Crow Lane A B-H reported that utility cables were hanging underneath the bridge and these could snag debris from up-stream causing a flood risk.	EA be asked to attend to the obstruction at the Wylye Bridge.	EA
5.	Bridge at Co-op Store  A-B H reported a buddleia growing from the bridge.	WC be asked to remove the buddleia bush.	WC
6.	Overflow Ditch – Naish Felts Bridge/Crow Lane A B-H reported that the overflow channel had not been cleaned of plant growth.	That Naish Felts Ltd be asked to clear the ditch	WTC
7.	Communications  A B-H suggested that information be sent to New Valley News advising affected householders of measure they can take to protect against flooding.	That the Clerk send a press release with advice leaflet to NVN for publication.	WTC
8.	WhatsApp It was suggested that members of the Flood Group and other emergency volunteers should have a WhatsApp Group to facilitate communications.	That a WhatsApp Group be set up.	WTC
9.	A30 Shaftesbury Road (lower section) - Nadder - Wylye. R A-B reported on longstanding issues with surface water drainage. PC advised 'Phase 1' has been completed (clearance of the highway surface water drainage culvert through 23 St John's Square, exiting into the River Wylye by C&O Tractors).	A meeting to discuss 'Phase 2' plans is being arranged PC, R A-B, Danny Everett & David Button.	RA-B/PC
10.	Wishford / Elizabeth / Philip / Olivier Roads.  R A-B reported on various surface water drainage issues impacting on Water Ditchampton from this hillside estate	To be discussed at the planned PC, R A-B, Danny Everett & David Button meeting.	RA-B/PC
11.	Water Ditchampton rear drainage channel.  R A-B reported on high silt levels affecting highway surface water drainage & also general drainage from the wider Water Ditchampton area. The rear drainage channel runs through the back gardens of 16 or so riparian landowners. EA advise method statements required before permission granted to dig to original ditch depth.	<ul><li>a) Dig out Side ditch next to Grovely Riding School WC/GRS</li><li>b) Waterditchampton riparian ditch dig out</li></ul>	WC/ GRS WTC/ WC/EA
12.	Grovely Downs Silt and Water Run-Off R A-B reported that additional works were required (and possibly a further catchment pond) to ameliorate the run-off and silt issues around the Grovely Riding Centre. R A-B reported silt build up in the catchment pond and suggested an additional catchment pond should be created. The grip in the paths was also overwhelmed by the current heavy rainfall and it was considered that a second grip may help reduce run-off into Wishford Road and the ditches at Waterditchampton.	<ul> <li>a) Catchment pond at the top of The Hollows track – dig out</li> <li>b) Installation of 2nd grip in Grovely Wood</li> <li>c) Installation of 2nd catchment pond</li> </ul>	-WE
13.	Shaftesbury Road/Nadder/Wylye surface water drainage PC reported that the first phase of works had been completed.	Phase 2 Shaftesbury Road/Nadder/Wylye surface water drainage	WC/EA

14.	River Wylye / Butcher Stream overflow into the (isolated) Water Ditchampton rear drainage channel.  Butcher Stream is described as a high level, carrier river. R  A-B confirmed that historical reports by local residents & Cllr Batchelder are correct - during high river levels,  Butcher Stream does overflow into Grovely Riding Centre's far horse field & then into the Water Ditchampton drainage channel. This is via an eroded point in the riverbank by the Salisbury - Warminster railway line.  Concerns that the impact on water levels & highway drainage in Water Ditchampton, potentially increases floodrisk.	R A-B to provide photo evidence from Butcher Stream overflows on 20/12/19 - 5/1/20 & 17/2/20 - ongoing, for review by relevant agencies.	R A-B
15.	Flouse Hole Ditch and Culvert  R A-B reported that the ditch in Flouse Hole played an important part in the effective drainage of this part of Waterditchampton and West Street, it was vital that the ditch is kept clear.	That Wilton Estate (Riparian Owners) be reminded of the need for this waterway to be maintained in late summer/early autumn each year.	WE
16.	Shaftesbury Road and St Johns Square Councillor Church reported that works to reconnect/improve outfalls had been completed.	To note	N/A
17.	<ul> <li>North Street</li> <li>Councillor Church reported:</li> <li>a) that the service strike to the road gully pipe crossing re No 47, has been repaired with the missing section of pipe (previously removed by SGN) now replaced and all reinstated as operational. Efforts will be made to recover the costs of these works from SGN.</li> <li>b) The "slow running" gully at the corner of Russell Street and under the church yard wall is still to be investigated fully and rectified. It's suspected that roots from the old yew trees in the churchyard are effecting that and the carrier drain running south to north alongside the church yard wall as well. This will be subject to excavation once a road closure of North Street can be arranged.</li> <li>c) The sink hole over an old pipe near the cross roads junction and Paloma Lily, was found to be a redundant drainage pipe and therefore sealed and back filled.</li> </ul>	Councillor Church will pursue these matters via Wiltshire Council.	N/A
18.	West Street Councillor Church reported that the investigation of collapsed carrier drains (caused by multiple utility strikes (SGN and BT) have been rectified between the betting shop and church on the south side and outside of the pet shop on the north side; however permanent reinstatement works have yet to follow.	To note	N/A

19.	Minster Street Councillor Church reported:  a) Works to gullies outside of Coffee Darling, etc. have been largely completed to make the apparatus secure in the carriageway, however some further reinstatement works are still to take place.	•	
	b) Drainage of highway surface water away from all the drains/gullies on the Pembroke Arms end of Minster Street (including from Four Corners eastwards) is still compromised by impeded flow within adjacent Wilton Estate parkland. Investigations of this have been partially undertaken, but a fall in surface and ground water levels is now required in the piped system before further progress can be made with investigation and ultimately rectification.	To note	N/A
20.	Drain Clearance A30 – Hingston's Antiques As well as the blocked slot drain on Hingston's front pavement, R A-B reported that the A30 highway gully by Hingston's car park needs properly emptying - WC ref. 797670, reported September 2016. Apparently gully tanker needs traffic management, but was missed in 2019 works. WC aware.	That WC be requested to clear the slot drain and empty the gully at Hingston's Car Park.	WC
21.	Burdens' Ball and Sheep Fair Field  A B-H reported that water was flowing from the Sheep Fair Field down the farm track at Burdens' Ball and into King Street. Carriageway drains had not been cleared sufficiently in this area to allow flow to the adjoining fields and as a consequence there were large puddles forming or the carriageway and pavement.	off from Burdens' Ball / Sheep Fair Field in this area to prevent	WC HE
		out of drainage system – HE	
22.	The Wilton Civil Emergency Plan The Group considered the draft flood element of the Wilton Civil Emergency Plan. Subject to the removal of statutory responsibilities, the plan was endorsed by the Group.	That the Council be requested to adopt the Wilton Flood Action Plan, subject to inclusion of a list of critical drainage ditches and gullies – with maintenance programme.	WTC 🗹
23.	Resourcing Resilience SM reported on the need to recruit trained volunteers to assist in times of emergency – whether that is flood, snow, pandemic, drought, fuel shortages, etc. Bradford on Avon had an active emergency volunteer group and it was decided to invite them to come and talk to the Group.	Invite the Bradford on Avon Community Emergency Volunteers to speak at a future meeting.	WTC

WTC Offices

Friday 24th April at 10am

WTC

24.

**Next Meeting**